



CAC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

**Certificate  
OCT 26 2004  
of Correction**

U.S. Patent No. : 6,767,784 B2  
Issued : July 27, 2004  
Title : **LATCH-UP PREVENTION FOR MEMORY CELLS**  
Docket No. : MIO 0042 V2/40509.141

**Certificate of Corrections Branch**  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**CERTIFICATE OF MAILING**  
I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on October 19, 2004.

James E. Beyer

Reg. No. 39,564

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE**  
**UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322**

In the matter of U.S. Patent No. 6,767,784 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

- Col. 2, line 2, "bipolar transistor and an" should read --bipolar transistor 20 and an--;
- Col. 11, line 58, "first voltage input V<sub>CC</sub>" should read -- first voltage input V<sub>CC</sub>--;
- Col. 12, line 42, "layer first" should read -- layer/first--;
- Col. 13, Claim 1, line 67, "conductivity," should read --conductivity;--; and
- Col. 13, Claim 2, line 25, "fanning" should read --forming--.

OCT 26 2004

Patent No. 6,767,784 B2  
Docket No. MIO 0042 V2/40509.141

**REMARKS**

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,  
DINSMORE & SHOHL LLP

By



James E. Beyer  
Registration No. 39,564

One Dayton Centre  
One South Main St., Suite 1300  
Dayton, Ohio 45402-2023  
Telephone: (937) 449-6400  
Facsimile: (937) 449-6405

JEB/vlh  
Encl.

OCT 26 2004

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,767,784 B2

DATED : July 27, 2004

INVENTOR(S) : Porter et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 2, "bipolar transistor and an" should read --bipolar transistor 20 and an--;

Col. 11, line 58, "first voltage input  $V_{CC}$ " should read -- first voltage input  $V_{CC}$ --;

Col. 12, line 42, "layer first" should read -- layer/first--;

Col. 13, Claim 1, line 67, "conductivity," should read --conductivity;--; and

Col. 13, Claim 2, line 25, "fanning" should read --forming--.

**MAILING ADDRESS OF SENDER:**

Dinsmore & Shohl LLP

One Dayton Centre

One South Main Street, Suite 1300

Dayton, Ohio 45402-2023

PATENT NO. 6,747,784 B2

No. of additional copies



1 of 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

**OCT 26 2004**

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,767,784 B2

DATED : July 27, 2004

INVENTOR(S) : Porter et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 2, "bipolar transistor and an" should read --bipolar transistor 20 and an--;

Col. 11, line 58, "first voltage input  $V_{CC}$ " should read -- first voltage input  $V_{CC}$ --;

Col. 12, line 42, "layer first" should read -- layer/first--;

Col. 13, Claim 1, line 67, "conductivity," should read --conductivity;--; and

Col. 13, Claim 2, line 25, "fanning" should read --forming--.

## MAILING ADDRESS OF SENDER:

Dinsmore &amp; Shohl LLP

One Dayton Centre

One South Main Street, Suite 1300

Dayton, Ohio 45402-2023

PATENT NO. 6,747,784 B2

No. of additional copies



1 of 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

OCT 26 2004